

Sections E through K: Complete on all inspections as appropriate (N/A = Not Applicable N/E = Not Evaluated)

E. PERMIT VERIFICATION

Inspection Observations Verify the Permit	Yes	No	N/A	N/E
a. Correct name and mailing address of permittee	X			
b. Correct name and location of receiving waters	X			
c. Product(s) and production rates conform with permit application (industries)	X			
d. Flows and loadings conform with NPDES permit	X			
e. Treatment processes are as described in permit application/briefing memo	X			
f. New treatment process(es) added since last inspection		X		
g. Notification given to state of new, different, or increased discharges	X			
h. All discharges are permitted	X			
i. Number and location of discharge points are as described in permit		X		

Comments: i. Outfall 012 is not a direct discharge, it discharges to pond 08.

F. COMPLIANCE SCHEDULES/VIOLATIONS

	Yes	No	N/A	N/E
a. Any significant violations since the last inspection		X		
b. Permittee is taking actions to resolve violations			X	
c. Permittee has compliance schedule		X		
d. Compliance schedule contained in: _____			X	
e. Permittee is meeting compliance schedule			X	

Comments:

G. OPERATION AND MAINTENANCE

Treatment Facility Properly Operated and Maintained	Yes	No	N/A	N/E
a. Standby power available: Generator: _____ Dual Feed: _____		X		
b. Adequate alarm system available for power or equipment failures	X			
c. All treatment units in service other than backup units	X			
d. Sufficient operating staff provided: No. of shifts: <u>1</u> Days/Week: <u>5</u>	X			
e. Operator holds unexpired license of class required by permit Class: <u>I</u>	X			
f. Routine and preventive maintenance schedule/performed on time	X			
g. Any major equipment breakdown since last inspection		X		
h. Operation and maintenance manual provided and maintained		X		
i. Any plant bypasses since last inspection		X		
j. Regulatory agency notified of bypasses: _____ on MORS _____ 800 No.			X	
k. Any hydraulic and/or organic overloads experienced since last inspection		X		

Comments: It is recommended that AEC hire a consultant to troubleshoot the sewage treatment plant.